

Pin 25-way	Pin 9-way	Input/Output	Symbol	Function
2	3	Out	TxD	Transmit Data
3	2	In	RxD	Receive Data
4	7	Out	RTS	Request To Send
5	8	In	CTS	Clear To Send
6	6	In	DSR	Data Set Ready
7	5		GND	Ground
8	1	In	DCD	Data Carrier Detect
20	4	Out	DTR	Data Terminal Ready
22	9	In	RI	Ring Indicator

